


VUV5k Flat Rate Repair

Certified maintenance and full factory test

Advantages:

- Fixed price
- Certified service by SO Engineer
- Including parts in High uptime kit
- Surfaces are checked and re-furbished*
- Vacuum Leak check
- Microwave Leak check
- Full Factory test
- Re-tuning of cavity*
- Test protocol
- Quick turnaround

**If needed*



VUV5050 Source Head



The VUV5050 source head needs regular maintenance for optimum performance. At our factory our experts are ready to inspect your VUV5050 in detail and go through a full factory test and tuning to make sure it is returned fully functional and in the best possible condition. All at a fixed price. A high uptime kit is included in the service and parts that are not used will be shipped together with the source as spares.

Summary

Part numbers:

- 200953 VUV5k source head Flat Rate Repair

Parts included:

- 200584 High uptime kit VUV5k source

Conditions:

- Including maintenance work and parts in 200584 High uptime kit VUV5k source, Leak check and functional test
- The Customer will arrange and take the cost for the shipment and return shipment of all equipment involved in this Service. No work on the item will be done unless the item is delivered together with the Scienta Omicron "Declaration of Decontamination" form. The form can be ordered from Scienta Omicron.

Onsite effort:

- Does not require SO Engineer on site

Options:

-

How to contact us:

www.scientaomicron.com

info@scientaomicron.com